Projection in GAN-3220 (DPL)

Nathan Borkholder (Student Employee) - 2026-01-20 - AV and Projection

To Connect the Teacher Station:

1. Make sure all TVs are turned on.
2. Select **Instructor Station** on the top bar of the control panel.
3. Tap **PC**
4. Tap **Send to all Displays**

To Connect a Laptop:

1. Make sure all TVs are turned on.
2. Plug the **USB-C connection** into the **laptop**
3. Select **Instructor Station** on the top bar of the control panel.
4. Tap **USBC Connection**
5. Tap **Send to all Displays**

Trouble Shooting:

- **If the sound isn't working.**
  - Make sure the mute button on the control panel is not red (red means muted)
  - Make sure **Extron** is selected as the output in the audio settings of your device (computer, laptop)
  - Make sure volume is not muted on the computer.
- **If the TV's aren't displaying:**
  - Repeat the steps above to connect the computer to the TVs but wait a few seconds before tapping each button on the screen.
  - Try unplugging the USB-C cable on the laptop or teacher station and then plug it back in

securely. Then tap **Send to all Displays**.

- If this still hasn’t worked please submit a ticket to CADTech.

Submit a ticket at **helpdesk.cad.rit.edu** If you are experiencing further issues.